

# Workplace Safety Card

## Identification of the substance/mixture

**Trade name**  
Sølvnitrat

**Usage**  
Laboratorier

**Emergency telephone**  
Call "Giftlinien" 8212 1212 (open 24 /7)

## Hazards identification

### Classification of the substance or mixture

Skin Corr. 1B; H314  
Eye Dam. 1; H318  
Aquatic Acute 1; H400  
Aquatic Chronic 1; H410  
; DGEBE



**Danger**

### Hazards

Causes severe skin burns and eye damage. (H314)  
Very toxic to aquatic life with long lasting effects. (H410)  
Do not use in paint spraying equipment. (DGEBE)

<b>Safety statements</b>	<b>General</b>	-
	<b>Prevention</b>	Do not breathe dust. (P260). Wear eye protection/protective clothing/protective gloves. (P280). IF SWALLOWED: Rinse mouth. Do NOT induce vomiting. (P301+P330+P331). IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water [or shower]. (P303+P361+P353).
	<b>Response</b>	IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. (P305+P351+P338).
	<b>Storage</b>	-
	<b>Disposal</b>	Dispose of contents/container to an approved waste disposal plant. (P501).
<b>Additional labelling</b>	-	

## Personal protective equipment



### Generally

Use only CE marked protective equipment.

### Respiratory equipment

Use in fumehood

### Skin protection

Dedicated work clothing should be worn. Wear a protective suit in the event of prolonged periods of work with the product.

### Hand protection

Recommended: Nitrile rubber. Breakthrough time: > 480 minutes (Class 6)

### Eye protection

Wear safety glasses with side shields.