

# Workplace Safety Card

## Identification of the substance/mixture

**Trade name**

2-Pentanol

**Usage**

Laboratorier

**Emergency telephone**

Call "Giftlinien" 8212 1212 (open 24 /7)

## Hazards identification

**Classification of the substance or mixture**

Acute Tox. 4, STOT SE 3, Flam. Liq. 3 // H302 + H312 + H332, EUH066, H335, H226

**Warning!****Hazards**

Flammable liquid and vapour. (H226)

May cause respiratory irritation. (H335)

Harmful if swallowed, in contact with skin or if inhaled. (H302 + H312 + H332)

**▼ Safety statements****General**

-

**Prevention**

Use only outdoors or in a well-ventilated area. (P271)

Avoid breathing dust/fume/gas/mist/vapours/spray. (P261)

IF INHALED: Remove victim to fresh air and keep at rest in a position comfortable for breathing. (P304+P340)

**Response**

Call a POISON CENTER or doctor/physician if you feel unwell. (P312)

**Storage**

Store in a well-ventilated place. Keep cool. (P403+P235)

**Disposal**

Dispose of contents/container to an approved waste disposal plant. (P501)

**Additional labelling**

Repeated exposure may cause skin dryness or cracking. (EUH066)

## Personal protective equipment

**Generally**

Only CE-marked personal protection equipment should be used.

**Respiratory equipment**

Recommended: Use in fumehood, -, -

**Skin protection**

Special work clothing should be used.

**Hand protection**

Recommended: Nitrile rubber. . Breakthrough time: &gt; 480 minutes (Class 6)

**Eye protection**

Use face shield. Use safety glasses with a side shield as an alternative.