

Workplace Safety Card

Identification of the substance/mixture

Trade name

Svovlsyre 90-100%

Usage

Laboratorier

Emergency telephone

Call "Giftnlinien" 8212 1212 (open 24 /7)

Hazards identification

Classification of the substance or mixture

Skin Corr. 1A; H314
Eye Dam. 1; H318
; DGEBE



Danger

Hazards

Causes severe skin burns and eye damage. (H314)
Do not use in paint spraying equipment. (DGEBE)

Safety statements	General	-
	Prevention	Do not breathe mist/vapours/fume/spray. (P260). Wash hands/exposed areas/exposed skin/hands and exposed skin thoroughly after handling. (P264). Wear eye protection/protective clothing/protective gloves. (P280). Immediately call a POISON CENTER/doctor. (P310).
	Response	IF SWALLOWED: Rinse mouth. Do NOT induce vomiting. (P301+P330+P331). IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water [or shower]. (P303+P361+P353). IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. (P305+P351+P338).
	Storage	-
	Disposal	Dispose of contents/container to an approved waste disposal plant. (P501).
Additional labelling	-	

Personal protective equipment



Generally

Use only CE marked protective equipment.

Respiratory equipment

Use in fumehood

Skin protection

Dedicated work clothing should be worn. Wear a protective suit in the event of prolonged periods of work with the product.

Hand protection

Recommended: Plastic gloves

Eye protection

Wear safety glasses with side shields.